

ABS Survey Manager

SURVEY STATUS REPORT

CHIMBORAZO

REGISTERED OWNER : EMPRESA PUBLICA FLOTA PETROLERA ECUATORIANA



Class Number : 9936460
IMO Number : 9174581
Print Date : Tue Sep 12 12:07:02 CDT 2017

THIS REPORT HAS BEEN PRODUCED FROM ABS SURVEY MANAGER AND IS SUBJECT TO ERRORS AND CHANGES THAT MAY OCCUR OUTSIDE THE ABS SURVEY MANAGER APPLICATION. ABS ASSUMES NO RESPONSIBILITY FOR ERRORS OR ACTIONS TAKEN BASED ON THE INFORMATION HEREIN. ABS'S ENTIRE RESPONSIBILITY AND LIABILITY IS GOVERNED BY THE LICENSE AGREEMENT FOR ABS SURVEY MANAGER.

ABS Survey Manager Survey Status

Name : CHIMBORAZO

Class Number : 9936460

Status : In-Operation - Lightering Service, Active, Classed

IMO Number : 9174581

Table of Contents

Owner/Manager Address	3
General Characteristics	3
Hull	6
Machinery	6
Capacity	7
Lifting Equipment.....	7
Certificates	8
Surveys - Scheduled	10
Attendance - In Progress	10
Surveys - Incomplete	10
Surveys - History	11
Surveys - Future	13
Survey Parts	14
Class Recommendations - Open	27
Class Recommendations - In Progress	27
Statutory Deficiencies - Open	27
Statutory Deficiencies - In Progress	27
Special Findings - Open	27
Special Findings - In Progress	27
Attendance History - Last 12 months	27
Request For Attendance	29

ABS Survey Manager Survey Status

Name	: CHIMBORAZO	Class Number	: 9936460
Status	: In-Operation - Lightering Service, Active, Classed	IMO Number	: 9174581

Owner/Manager Address

Owning Company

**EMPRESA PUBLICA FLOTA PE
TROLERA ECUATORIANA**

Customer Number : 215526
Attention : ACCOUNTS PAYABLE,
Address :

RUC: 1768164300001
AV. DEL PACIFICO 001 Y
PUERTO RICO
EDIFICIO EP FLOPEC, MA
LECON LAS PALMAS
ESMERALDAS, Ecuador.

Registered Owning Company

**EMPRESA PUBLICA FLOTA PE
TROLERA ECUATORIANA**

Customer Number : 215526
Attention : ACCOUNTS PAYABLE,
Address :

RUC: 1768164300001
AV. DEL PACIFICO 001 Y
PUERTO RICO
EDIFICIO EP FLOPEC, MA
LECON LAS PALMAS
ESMERALDAS, Ecuador.

Account Manager

**EMPRESA PUBLICA FLOTA PETR
OLERA ECUATORIANA**

Name (first,last): Edgar Jarrin
Phone : 593987518636
E-mail : vetting@flopec.com.ec
WCN : 215526

Address :

RUC: 1768164300001
AV. DEL PACIFICO 001 Y
PUERTO RICO
EDIFICIO EP FLOPEC, MA
LECON LAS PALMAS
ESMERALDAS, Ecuador.

Billing Customer

**EMPRESA PUBLICA FLOTA PE
TROLERA ECUATORIANA**

Customer Number : 215526
Attention : ACCOUNTS PAYABLE,
Address :

RUC: 1768164300001
AV. DEL PACIFICO 001 Y
PUERTO RICO
EDIFICIO EP FLOPEC, MA
LECON LAS PALMAS
ESMERALDAS, Ecuador.

General Characteristics

Designation

Official Registry Number	TI-00-00001
Call Sign	HCCH
Flag Name	Ecuador
Port of Registration	Guayaquil
Date Of Registry	

Keel Laying Date	24 Mar 1999
Delivery Date	20 Sep 1999

Categories

Description	Double Hull Oil Carrier
SOLAS CATEGORY	Oil Tanker
MARPOL CATEGORY	Crude Oil Tanker
IBC IGC CATEGORY	Not Applicable
ISM CATEGORY	Oil Tanker

ABS Class Notations

✚ A1,Oil Carrier,ESP,Ⓢ , ✚ AMS, ✚ ACC,SH

ABS Notations

RRDA, CRC, VEC

Service Limit

Unrestricted Service

ABS Survey Manager Survey Status

Name : CHIMBORAZO Class Number : 9936460
Status : In-Operation - Lightering Service, Active, Classed IMO Number : 9174581

ABS Safety, Quality and/or Environmental Standards:

International code for the security of the ships and of port facilities (ISPS Code), ABS Security Notation:

Lightering Service History Information

Added Service Date	Removed Service Date
--------------------	----------------------

07 Aug 2017

Anchor Equipment

Equipment Numeral U-41
Anchor Holding Ability Superior (RW)
Design Nominal Chain Diameter 52.39 mm
Strength Level Extra-high Strength

Other Info

Rapid Response Program Yes

Principal Characteristics

Estimated Gross Tonnage 36817.89 tonnes
Design Deadweight 66138 tonnes
Length between perpendicular 219 m
Molded Breadth(M) 32.2
Molded Depth(M) 17.85
Bulb Length From FP 4.5 m
Web Frame Depth 1.1 m

Tonnage

Regulation	Gross Tonnage	Net Tonnage
ITC	35770 (Registered)	20199 (Registered)
PANAMA		29665
SUEZ	36817.89	32497.08

Loading Application and Manual/Reference

Loading Manual Yes
Loading Instrument Yes
Trim and Stability Booklet Yes

Builder

Builder	Customer Number	Builder Building ID	Builder Role	Project Description	Contractual Responsibility	Contract Date
HYUNDAI HEAVY IND. CO., LTD.	285412	1129	Prime Build			24 Mar 1999

Functions

Oil (F.P. 60oC or less)

IACS Unified Requirements Information

No IACS Unified Requirements found for this vessel.

IMO Requirements Information

No IMO Requirements found for this vessel.

ABS Survey Manager Survey Status

Name	: CHIMBORAZO	Class Number	: 9936460
Status	: In-Operation - Lightering Service, Active, Classed	IMO Number	: 9174581

Freeboard Assignments

<u>Freeboard</u>	<u>Displacement</u>	<u>Deadweight (tonnes)</u>	<u>Calculated Freeboard(mm)</u>	<u>State</u>
	78336	66138	4.916	Available

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Hull

Material

<u>Type</u>	<u>Primary</u>	<u>Location</u>
High Strength Steel	No	Class - High Strength Steel - Standard -Not Specified - Grade -Not Specified, Location Field - Please verify location with ships Drawing or contact CDC for location information.
Ordinary Strength Steel	Yes	

Stiffener Systems

On Side Shell : Longitudinal

Bulkhead

<u>Type</u>	<u>Number</u>
Non Tight	2
Oil Tight	10

Tank

<u>Type</u>	<u>Number</u>
Cargo Oil	12
Ballast	10
Fuel Oil	7
Lubricating Oil	5
Fresh Water	3
Diesel Oil	3
Waste Water	2
Slop	2
Chain	1
Sludge	1

Machinery

Propulsion System

MAIN ENGINE

Manufacturer Name :	HHI ENGINE & MACHINERY DIV.	Model Number :	5S60MC
Cylinder Bore:	600 mm	Maximum Continuous Rating:	9116.12 kW
Number of Cylinders:	5	Piston Stroke:	2292 mm
Revolutions at MCR:	rpm		

PROPELLER

Propeller Design Speed:	14.5 knots	Propeller Material (ABS Grade):	Bronze
-------------------------	------------	---------------------------------	--------

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Tail Shaft

Propeller Shaft Bearing

Bearing Lubricant: Oil

Steam Piping System

Auxiliary Water Tube Boiler P

Manufacturer Name : Aalborg Sunrod AB Model Number : CPH
 Manufacture Number : 4098
 Maximum Allowable 16 bar
 Working Pressure:

Auxiliary Water Tube Boiler S

Manufacturer Name : Aalborg Sunrod AB Model Number : CPH
 Manufacture Number : 4097
 Maximum Allowable 16 bar
 Working Pressure:

Waste Heat Boiler¹

Manufacturer Name : KANGRIM INDUSTRIES
 CO LTD
 Manufacture Number : EM7HD073
 Maximum Allowable 22 bar
 Working Pressure:

Main Power Distribution System

Aux Generator No 01 PORT¹

Rated Power: 600 kW

Aux Generator No 02 CENTER¹

Rated Power: 600 kW

Aux Generator No 03 STBD¹

Rated Power: 600 kW

Capacity

Compartment Capacity	Volume 100% Full(CuM)	Weight 100% Full(tonnes)
Cargo Oil Capacity	72213	67880.22
Freshwater Capacity	299	293.02
Fuel Oil Capacity	1973	1854.62
Tank Ballast Capacity	26791	26791

Lifting Equipment

Crane¹

Safe Working Load : 15 tonnes

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Certificate Type	Term	Flag	Issue Date	Expiry Date	Extended Date	State Date	Status
Classification							
Class Certificate	Full Term		19 Aug 2014	08 May 2019		07 Aug 2017	Annual Endorsement
Narrative Report - Statement of Fact	Full Term		22 Apr 2014			22 Apr 2014	Issued
Narrative Report - Statement of Fact	Full Term		22 Apr 2014			22 Apr 2014	Issued
Narrative Report - Statement of Fact	Full Term		25 Dec 2016			25 Dec 2016	Issued
Narrative Report - Statement of Fact	Full Term		25 Dec 2016			25 Dec 2016	Issued
Marpol							
Statement of Voluntary Compliance of Air Pollution Prevention (Annex VI - HSSC)	Full Term	Ecuador	24 Apr 2016	08 May 2019		22 Apr 2017	Intermediate Endorsement
Statement of Voluntary Compliance of Air Pollution Prevention (Annex VI - HSSC) - Supplement	Full Term	Ecuador	24 Apr 2016			24 Apr 2016	Issued
Cargo Gear							
Register of Lifting Appliances			24 Apr 2016			24 Apr 2016	Annual Endorsement
Cargo Gear Certificate - Annual			22 Apr 2017			22 Apr 2017	Issued
Cargo Gear Certificate - Retesting			31 Jul 2017	29 Jul 2021		31 Jul 2017	Issued
Others							
Narrative Report - Statement of Fact	Full Term	Ecuador	03 Jun 2009			03 Jun 2009	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	03 Jun 2009			03 Jun 2009	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	22 Jul 2009			22 Jul 2009	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	14 May 2010			14 May 2010	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	12 Dec 2011			12 Dec 2011	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	12 Dec 2011			12 Dec 2011	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	12 Dec 2011			12 Dec 2011	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	20 Jul 2016			20 Jul 2016	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	25 Dec 2016			25 Dec 2016	Issued
Record of Anti-Fouling Systems	Full Term	Ecuador	21 Apr 2014			21 Apr 2014	Issued

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Certificate Type	Term	Flag	Issue Date	Expiry Date	Extended Date	State Date	Status
Statement of Voluntary Compliance of Anti-Fouling System	Full Term	Ecuador	21 Apr 2014			21 Apr 2014	Issued
Record of Anti-Fouling Systems	Full Term	Ecuador	25 Dec 2016			25 Dec 2016	Issued
Statement of Voluntary Compliance of Anti-Fouling System	Full Term	Ecuador	25 Dec 2016			25 Dec 2016	Issued

ABS Survey Manager Survey Status

Name : **CHIMBORAZO**















Class Number : **9936460**

Status : **In-Operation - Lightering Service, Active, Classed**

IMO Number : **9174581**

Surveys - Scheduled

 indicates survey requested or in progress.

Survey Name	Status	Last Visit Date	Due Date	Range Date	Extended Date
Classification					
Annual Automation Survey 4			08 May 2018	08 Feb 2018 - 08 Aug 2018	
Annual Hull Survey 4			08 May 2018	08 Feb 2018 - 08 Aug 2018	
Annual Machinery Survey 4			08 May 2018	08 Feb 2018 - 08 Aug 2018	
Boiler Survey - Auxiliary Water Tube Boiler P			08 May 2019		
Boiler Survey - Auxiliary Water Tube Boiler S			08 May 2019		
Boiler Survey - Waste Heat Boiler			08 May 2019		
Drydocking Survey			08 May 2019		
Special Continuous Survey - Machinery 4		Commenced 07 Aug 2017	08 May 2019	08 Feb 2019 - 08 May 2019	
Special Periodical Survey - Automation 4			08 May 2019	08 Feb 2018 - 08 May 2019	
Special Periodical Survey - Hull 4			08 May 2019	08 Feb 2018 - 08 May 2019	
Tailshaft Survey - Tail Shaft - Oil		Extended	02 Jun 2014		21 Apr 2019
Statutory					
Annual IAPP Annex VI Survey 4			21 Apr 2018	21 Jan 2018 - 21 Jul 2018	
Renewal IAPP Annex VI Survey 4			21 Apr 2019	21 Jan 2019 - 21 Apr 2019	
Miscellaneous					
Cargo Gear Survey		07 Aug 2017	22 Apr 2018		

Attendance - In Progress

No records exist for the criteria.

Surveys - Incomplete

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Survey Name	Due Date	Status	Report Number	Report Date	Location
Special Continuous Survey - Machinery 4	08 May 2019	Commenced	VP3360517-D	07 Aug 2017	Valparaiso

To complete Special Continuous Survey - Machinery 4 the following checklist items remains to be dealt with, checklist item sequence numbers 1, 2, 3, 4, 5, 6, 7, 8, 9, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 30, 31, 32, 34, 35, 36, 37, 38, 39, 40, 46, 53, 54, 64, 75, 76, 77, 78, 79, 86, 87

Surveys - History For Last 5 Years

Survey Name	Status	Last Visit Date	Done Date	Location	Report Number
Classification					
Annual Automation Survey 3	Completed		07 Aug 2017	Valparaiso	VP3360517-E
Annual Hull Survey 3	Completed		07 Aug 2017	Valparaiso	VP3360517-C
Annual Machinery Survey 3	Completed		07 Aug 2017	Valparaiso	VP3360517-B
Special Continuous Survey - Machinery 4	Commenced	07 Aug 2017		Valparaiso	VP3360517-D
Special Continuous Survey - Machinery 4	Commenced	10 May 2017		San Francisco, CA	SF3325476-B
Boiler Survey - Auxiliary Water Tube Boiler S	Completed		22 Apr 2017	Balboa	BL3319296.R1-B
Special Continuous Survey - Machinery 4	Commenced	22 Apr 2017		Balboa	BL3319296.R1-C
Boiler Survey - Waste Heat Boiler	Completed		02 Feb 2017	Balboa	BL3279108-A
Boiler Survey - Auxiliary Water Tube Boiler P	Completed		25 Dec 2016	Balboa	BL3243190-D
Boiler Survey - Auxiliary Water Tube Boiler S	Commenced	25 Dec 2016		Balboa	BL3243190-E
Boiler Survey - Waste Heat Boiler	Commenced	25 Dec 2016		Balboa	BL3243190-F
Drydocking Survey	Completed		25 Dec 2016	Balboa	BL3243190-C
Intermediate Hull Survey 4	Completed		25 Dec 2016	Balboa	BL3243190-B
Special Continuous Survey - Machinery 4	Commenced	25 Dec 2016		Balboa	BL3243190-A
Annual Automation Survey 2	Completed		20 Jul 2016	Guayaquil	GY3175353-D
Annual Hull Survey 2	Completed		20 Jul 2016	Guayaquil	GY3175353-B
Annual Machinery Survey 2	Completed		20 Jul 2016	Guayaquil	GY3175353-A
Special Continuous Survey - Machinery 4	Commenced	20 Jul 2016		Guayaquil	GY3175353-C
Special Continuous Survey - Machinery 4	Commenced	24 May 2016		Guayaquil	GY3144444-A
Special Continuous Survey - Machinery 4	Commenced	24 Apr 2016		Balboa	BL3127499-B
Annual Hull Survey 1	Completed		25 Jun 2015	Callao	CA2933268-B
Annual Machinery Survey 1	Completed		25 Jun 2015	Callao	CA2933268-A
Annual Automation Survey 1	Completed		10 Jun 2015	Callao	CA2922232-B
Annual Machinery Survey 1	Commenced	10 Jun 2015		Callao	CA2922232-A
Special Continuous Survey - Machinery 4	Completed		09 May 2014	Algeciras	AG2614685-A

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Survey Name	Status	Last Visit Date	Done Date	Location	Report Number
3					
Annual Automation Survey 5	Completed		21 Apr 2014	Algeciras	AG2566308-F
Annual Hull Survey 5	Completed		21 Apr 2014	Algeciras	AG2566308-G
Annual Machinery Survey 5	Completed		21 Apr 2014	Algeciras	AG2566308-H
Boiler Survey - Auxiliary Water Tube Boiler P	Completed		21 Apr 2014	Algeciras	AG2566308-L
Boiler Survey - Auxiliary Water Tube Boiler S	Completed		21 Apr 2014	Algeciras	AG2566308-M
Boiler Survey - Waste Heat Boiler	Completed		21 Apr 2014	Algeciras	AG2566308-N
Drydocking Survey	Completed		21 Apr 2014	Algeciras	AG2566308-I
Special Continuous Survey - Machinery	Commenced	21 Apr 2014		Algeciras	AG2566308-B
3					
Special Periodical Survey - Automation	Completed		21 Apr 2014	Algeciras	AG2566308-A
3					
Special Periodical Survey - Hull 3	Completed		21 Apr 2014	Algeciras	AG2566308-C
Annual Automation Survey 4	Completed		04 Nov 2013	Rio de Janeiro	RJ2475588-C
Annual Hull Survey 4	Completed		04 Nov 2013	Rio de Janeiro	RJ2475588-B
Annual Machinery Survey 4	Completed		04 Nov 2013	Rio de Janeiro	RJ2475588-A
Special Continuous Survey - Machinery	Commenced	04 Nov 2013		Rio de Janeiro	RJ2475588-E
3					
Special Continuous Survey - Machinery	Commenced	24 Jul 2013		Guayaquil	GY2405678-A
3					
Annual Automation Survey 3	Completed		26 Nov 2012	Guayaquil	GY2243388.R1-D
Annual Hull Survey 3	Completed		26 Nov 2012	Guayaquil	GY2243388.R1-B
Annual Machinery Survey 3	Completed		26 Nov 2012	Guayaquil	GY2243388.R1-A
Special Continuous Survey - Machinery	Commenced	26 Nov 2012		Guayaquil	GY2243388.R1-C
3					
Special Continuous Survey - Machinery	Commenced	19 Oct 2012		Balboa	BL2217536-A
3					
Special Continuous Survey - Machinery	Commenced	24 Jul 2012		Buenos Aires	BN2180025-A
3					
Special Continuous Survey - Machinery	Commenced	29 Dec 2011		Valparaiso	VP2085733_C
3					
Special Continuous Survey - Machinery	Commenced	12 Dec 2011		Valparaiso	VP2063842_H
3					
Special Continuous Survey - Machinery	Commenced	25 Oct 2011		Guayaquil	GY2057898_A
3					
Special Continuous Survey - Machinery	Commenced	13 Jun 2011		Guayaquil	GY2000628_B
3					
Special Continuous Survey - Machinery	Commenced	09 Feb 2011		Guayaquil	GY1945842_B
3					
Special Continuous Survey - Machinery	Commenced	13 Dec 2010		Guayaquil	GY1921938_C
3					
Statutory					
Intermediate IAPP Annex VI Survey 4	Completed		22 Apr 2017	Balboa	BL3319296.R1-D
Annual IAPP Annex VI Survey 2	Completed		24 Apr 2016	Balboa	BL3127499-C
Annual IAPP Annex VI Survey 1	Completed		10 Jun 2015	Callao	CA2922232-C

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Survey Name	Status	Last Visit Date	Done Date	Location	Report Number
Renewal IAPP Annex VI Survey 3	Completed		09 May 2014	Algeciras	AG2614685-B
Renewal IAPP Annex VI Survey 3	Commenced	21 Apr 2014		Algeciras	AG2566308-J
Annual IAPP Annex VI Survey 4	Completed		04 Nov 2013	Rio de Janeiro	RJ2475588-D
Intermediate IAPP Annex VI Survey 3	Completed		26 Nov 2012	Guayaquil	GY2243388.R1-E
Miscellaneous					
Cargo Gear Survey	Completed		07 Aug 2017	Valparaiso	VP3360517-A
Cargo Gear Survey	Completed		22 Apr 2017	Balboa	BL3319296.R1-A
Cargo Gear Survey	Completed		24 Apr 2016	Balboa	BL3127499-A
Cargo Gear Survey	Completed		26 Apr 2015	Callao	CA2888061-A
Cargo Gear Survey	Completed		21 Apr 2014	Algeciras	AG2566308-K
Cargo Gear Survey	Completed		29 Jul 2013	Guayaquil	GY2409310-A
Cargo Gear Survey	Completed		24 Jul 2012	Buenos Aires	BN2180025-B
Cargo Gear Survey	Completed		13 Jun 2011	Guayaquil	GY2000628_A
Cargo Gear Survey	Completed		28 Jun 2010	Guayaquil	GY1849505_A
Cargo Gear Survey	Completed		03 Jun 2009	Balboa	BL1674735_K
Cargo Gear Survey	Completed		03 Aug 2008	Guayaquil	GY1036321_A
Cargo Gear Survey	Completed		11 Aug 2007	Valparaiso	VP862284.R1_L
Cargo Gear Survey	Completed		24 Oct 2006	Guayaquil	GY759169_F
Cargo Gear Survey	Completed		27 Nov 2005	Guayaquil	GY659740_A
Cargo Gear Survey	Completed		25 Oct 2004	Valparaiso	VP553038_S
Cargo Gear Survey	Completed		26 Nov 2003	Guayaquil	GY478927_A
Cargo Gear Survey	Commenced	04 Oct 2002		Valparaiso	VP283111_K
Cargo Gear Survey	Completed		03 Sep 2001	Guayaquil	GY-01072
Cargo Gear Survey	Completed		03 Sep 2001	Guayaquil	GY-01072

Surveys - Future

Survey Name	Interval	Due Date	Left Range Date	Right Range Date	Extended Date
Classification					
Annual Automation Survey 4	12	08 May 2018	08 Feb 2018	08 Aug 2018	
Annual Automation Survey 5	12	08 May 2019	08 Feb 2019	08 May 2019	
Annual Hull Survey 4	12	08 May 2018	08 Feb 2018	08 Aug 2018	
Annual Hull Survey 5	12	08 May 2019	08 Feb 2019	08 May 2019	
Annual Machinery Survey 4	12	08 May 2018	08 Feb 2018	08 Aug 2018	
Annual Machinery Survey 5	12	08 May 2019	08 Feb 2019	08 May 2019	
Boiler Survey - Auxiliary Water Tube Boiler P		08 May 2019			
Boiler Survey - Auxiliary Water Tube Boiler S		08 May 2019			
Boiler Survey - Waste Heat Boiler		08 May 2019			
Drydocking Survey	36	08 May 2019			
Special Periodical Survey - Automation 4	60	08 May 2019	08 Feb 2018	08 May 2019	
Special Periodical Survey - Hull 4	60	08 May 2019	08 Feb 2018	08 May 2019	

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Survey Name	Interval	Due Date	Left Range Date	Right Range Date	Extended Date
Tailshaft Survey - Tail Shaft	60	02 Jun 2014			21 Apr 2019
Statutory					
Annual IAPP Annex VI Survey 4	12	21 Apr 2018	21 Jan 2018	21 Jul 2018	
Renewal IAPP Annex VI Survey 4	60	21 Apr 2019	21 Jan 2019	21 Apr 2019	

Survey Parts

Survey Parts : Special Continuous Survey - Machinery 4

Outfitting Item(s)	Inspection Type	Status	Due Date	Extended Date	Next Due Date
--------------------	-----------------	--------	----------	---------------	---------------

Fire Fighting Appliances

Breathing Apparatus (Count: 1)	Examination		30 Oct 2018		
Fire Extinguishers (Count: 1)	Examination		30 Oct 2018		
Fireman's Outfit (Count: 1)	Examination		30 Oct 2018		
International Shore Connection (Count: 1)	Examination		30 Oct 2018		

Log Book/Calibration Record

Camshaft Timing Record	Examination		25 Mar 2019		
Insulation Resistance Reading of Circuit	Examination		25 Mar 2019		

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
-------------------	--------	----------	---------------	---------------	----------------------

Ballast System

Ballast Piping ¹		21 Apr 2019			
Ballast Pump No 01 Inbd		25 Jul 2018			
Ballast Pump No 02 Outbd	Credited			07 Jul 2021	
Sea Chests ¹		21 Apr 2019			
Sea Valves ¹		21 Apr 2019			

Battery System

Batteries		21 Apr 2019			
-----------	--	-------------	--	--	--

Bilge System

Bilge Piping ¹		25 Mar 2019			
Bilge Suction Valve		25 Mar 2019			
Fire,General Service & Bilge Pump #1 Inbd		25 Mar 2019			
¹					
Fire,General Service & Bilge Pump #2 Outbd ¹		25 Mar 2019			

Boiler Feed Water System

Boiler Feed Pump No 01 Inbd		25 Mar 2019			
Boiler Feed Pump No 02 Outbd		24 Jul 2018			
Boiler Feed Water Piping ¹		24 Jul 2018			
Boiler Water Circulator No. 01 Outbd		21 Apr 2019			
Boiler Water Circulator No. 02 Inbd		25 Mar 2019			

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
Waste Heat Boiler Feed Pump No.01 Inbd		24 Jul 2018			
Waste Heat Boiler Feed Pump No.02 Outbd		24 Jul 2018			
Boiler Fuel Oil Service Piping System		21 Apr 2019			
Boiler Fuel Oil Heater #1 Upper ¹	Credited			13 Jun 2021	
Boiler Fuel Oil Heater #2 Lower ¹	Credited			13 Jun 2021	
Boiler Fuel Oil Service Pump No 01 Fwd		26 Nov 2018			
Boiler Fuel Oil Service Pump No 02 Aft		24 Jul 2018			
Boiler Lsmgo Cooler ¹		21 Apr 2019			
Boiler Lsmgo Cooler - Press. Test ¹		21 Apr 2019			
Boiler Lsmgo Pump No.01 Stbd		21 Apr 2019			
Boiler Lsmgo Pump No.02 Port		21 Apr 2019			
Boiler Fuel Oil Service Piping ¹		03 Aug 2018			
Cargo Area Foam System - Ops. Test¹		21 Apr 2019			
Cargo Area Foam System		21 Apr 2019			
Cargo Oil Stripping System					
Cargo Oil Stripping Piping ¹	Credited			15 Nov 2020	
Cargo Stripping Pump	Credited			15 Nov 2020	
Cargo Tank Venting System		21 Apr 2019			
Compressed Air System					
Compressed Air Piping ¹		25 Mar 2019			
Emergency Compressed Air Tank Qkclsvalv ¹		25 Mar 2019			
Emergency Compressed Air Tank Relief Vavles Qkclsvalv		25 Mar 2019			
Condensate System					
Air Ejector Condnsr&	Credited			12 Dec 2021	
Atmospheric Condenser	Credited			05 Mar 2022	
Aux Condensate Pump No 01 #1s Copt		25 Mar 2019			
Aux Condensate Pump No 02 #2p Copt		30 Oct 2018			
Aux Condenser Vacuum	Credited			05 Mar 2022	
Condensate Piping ¹		25 Mar 2019			
Ejector Pump Fw Genrtr	Credited			02 Jul 2022	
Cooling System					
Fresh Water Cooler No.01 Outbd ¹		21 Apr 2019			
Fresh Water Cooler No.02 Inbd ¹	Credited			11 Dec 2021	
Fresh Water Cooling Pump Port Use	Credited			02 Jul 2022	
Jacket Cooling Pump No.01 Fwd M/E		25 Mar 2019			
Jacket Cooling Pump No.02 Aft M/E		24 Jul 2018			
Crude Oil Washing System - Ops. Test¹		21 Apr 2019			
Crude Oil Washing System		21 Apr 2019			
Cow Piping - On Deck ¹		21 Apr 2019			
Emergency Power Distribution System					
Emergency Generator Engine With Attachments	Credited			07 Aug 2022	
Emergency Shutdown System					
Cargo Oil Pump Emergency Trip	Credited			07 Aug 2022	
Fire Main System		25 Mar 2019			
Fire Emergency Pump ¹		25 Mar 2019			
Fire Main Piping ¹		25 Mar 2019			

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
Fixed Gas Fire Extinguishing System		21 Apr 2019			
Fresh Water Cooling System					
Main Fresh Water Circulating Pump No 01 Ob Centr		30 Oct 2018			
Main Fresh Water Circulating Pump No 02 Ib Centr		21 Apr 2019			
Fresh Water System					
Evaporator No 01 Ob Fwgen	Credited			15 Nov 2020	
Evaporator No 02 Ib Fwgen	Credited			15 Nov 2020	
Fresh Water Piping ¹	Credited			15 Nov 2020	
Fuel Oil Service System		30 Oct 2018			
Fuel Oil Booster Pump No.01 Fwd G/E	Credited			12 Dec 2021	
Fuel Oil Booster Pump No.02 Aft G/E	Credited			05 Mar 2022	
Fuel Oil Circulating Pump No 01 Fwd M/E	Credited			30 Mar 2022	
Fuel Oil Circulating Pump No 02 Aft M/E	Credited			30 Mar 2022	
Fuel Oil Service Piping ¹	Credited			05 Mar 2022	
Fuel Oil Supply Pump No 01 Fwd G/E	Credited			02 Jul 2022	
Fuel Oil Supply Pump No 01 Fwd M/E	Credited			02 Jul 2022	
Fuel Oil Supply Pump No 02 Aft G/E		24 Jul 2018			
Fuel Oil Supply Pump No 02 Aft M/E		19 Oct 2017			
Fuel Oil Storage And Transfer System					
Diesel Oil Pump G/E Flush		25 Mar 2019			
Diesel Oil Transfer Pump		25 Mar 2019			
Fuel Oil Heater #1lwr G/E ¹	Credited			13 Jun 2021	
Fuel Oil Heater #1lwr M/E ¹	Credited			13 Jun 2021	
Fuel Oil Heater #2upr G/E ¹	Credited			13 Jun 2021	
Fuel Oil Heater #2upr M/E ¹	Credited			13 Jun 2021	
Fuel Oil Storage And Transfer Piping ¹		21 Apr 2019			
Heater For Fuel Oil Purifier #1 Lower ¹	Credited			13 Jun 2021	
Heater For Fuel Oil Purifier #2 Upper ¹	Credited			13 Jun 2021	
Heater Tankclean		04 Oct 2017			
Heavy Oil Transfer Pump		24 Jul 2018			
Purifier No 01 For Fuel Oil	Credited			12 Dec 2021	
Purifier No 02 For Fuel Oil	Credited			12 Dec 2021	
Generic System					
Pump Oilybilge	Credited			12 Dec 2021	
Pump Sludge		25 Mar 2019			
Inert Gas System - Ops. Test ¹		21 Apr 2019			
Inert Gas System		21 Apr 2019			
Automatic Control Valves		21 Apr 2019			
Deck Water Seal		24 Jul 2018			
Expansion Joints		21 Apr 2019			
Fan Drives - Megger Reading		21 Apr 2019			
Fan Drives		21 Apr 2019			
Fans		09 May 2019			
Inert Gas Piping ¹		21 Apr 2019			
Non-Return Valves		24 Jul 2018			
P/V Breaker - Ops. Test ¹		21 Apr 2019			
P/V Breaker		26 Nov 2018			

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
Pump Igsdkseal No. 2		08 May 2019			
Pump Igsdkseal No.1		08 May 2019			
S.W.Circulating Pump		24 Jul 2018			
Scrubber		26 Nov 2018			
Lubricating Oil Service System					
Camshaft Lube Oil Pump #1 Outbd		24 Jul 2018			
Camshaft Lube Oil Pump #2 Inbd		24 Jul 2018			
Lube Oil Pump #1s Main	Credited			07 Aug 2022	
Lube Oil Pump #2p Main		21 Apr 2019			
Lubricating Oil Service Piping ¹		25 Mar 2019			
Main Lube Oil Cooler ¹	Credited			05 Mar 2022	
Lubricating Oil Storage And Transfer System					
Heater For Lube Oil Purifier G/E ¹	Credited			13 Jun 2021	
Heater For Lube Oil Purifier No.1 M/E ¹	Credited			13 Jun 2021	
Lube Oil Purifier Pump Ge Supply		25 Mar 2019			
Lube Oil Purifier Pump Me Supply		24 Jul 2018			
Lube Oil Transfer Pump		24 Jul 2018			
Lubricating Oil Storage And Transfer Piping ¹		25 Mar 2019			
Purifier No 01 For Lube Oil M/E	Credited			12 Dec 2021	
Purifier No 02 For Lube Oil G/E	Credited			12 Dec 2021	
Main Power Distribution System					
Aux Generator Diesel No 01 With Attachments Port	Credited			02 Jul 2022	
Aux Generator Diesel No 02 With Attachments Center		11 Aug 2017			
Aux Generator Diesel No 03 With Attachments Stbd		25 Jul 2018			
Aux Switchboard		25 Mar 2019			
Electric Cables		25 Mar 2019			
Electric Fixtures		25 Mar 2019			
Electric Motors - Megger Reading		26 Nov 2018			
Electric Motors		26 Nov 2018			
Generator Trip No 01 - Reverse Power Protection		30 Oct 2018			
Generator Trip No 01 - Undervoltage Protection		30 Oct 2018			
Generator Trip No 02 - Reverse Power Protection	Credited			07 Aug 2022	
Generator Trip No 02 - Undervoltage Protection	Credited			07 Aug 2022	
Generator Trip No 03 - Reverse Power Protection	Credited			07 Aug 2022	
Generator Trip No 03 - Undervoltage Protection	Credited			07 Aug 2022	
Main Switchboard		21 Apr 2019			
Main Propulsion System					
Camshaft - Timing Record		21 Apr 2019			

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
Crankcase Relief Valves		25 Mar 2019			
Crankshaft - Deflection		25 Mar 2019			
Exhaust Manifold		30 Oct 2018			
Foundation Bolts		25 Jul 2018			
Foundation Chocks		25 Jul 2018			
Line Shaft Bearings		25 Mar 2019			
Line Shafting		25 Mar 2019			
Main Engine					
Cylinder Unit #1					
Crank Pin #1 ¹		25 Mar 2019			
Crosshead #1		21 Apr 2019			
Cylinder #1	Credited			09 Feb 2021	
Cylinder Head #1	Credited			09 Feb 2021	
Cylinder Liner #1	Credited			09 Feb 2021	
Cylinder Relief Valve #1 ¹	Credited			09 Feb 2021	
Exhaust Valve #1	Credited			11 Dec 2021	
Fuel Injection Pump #1	Credited			09 Feb 2021	
Fuel Injection Valve #1	Credited			12 Dec 2021	
Piston #1	Credited			09 Feb 2021	
Cylinder Unit #2					
Crank Pin #2 ¹	Credited			07 Aug 2022	
Crosshead #2	Credited			12 Dec 2021	
Cylinder #2	Credited			24 May 2021	
Cylinder Head #2	Credited			24 May 2021	
Cylinder Liner #2	Credited			24 May 2021	
Cylinder Relief Valve #2 ¹	Credited			24 May 2021	
Exhaust Valve #2	Credited			15 Nov 2020	
Fuel Injection Pump #2	Credited			13 Jun 2021	
Fuel Injection Valve #2	Credited			13 Jun 2021	
Piston #2	Credited			24 May 2021	
Cylinder Unit #3					
Crank Pin #3 ¹		25 Jul 2018			
Crosshead #3		21 Apr 2019			
Cylinder #3	Credited			13 Dec 2020	
Cylinder Head #3	Credited			13 Dec 2020	
Cylinder Liner #3	Credited			13 Dec 2020	
Cylinder Relief Valve #3 ¹	Credited			13 Dec 2020	
Exhaust Valve #3	Credited			13 Dec 2020	
Fuel Injection Pump #3	Credited			13 Dec 2020	
Fuel Injection Valve #3	Credited			13 Dec 2020	
Piston #3	Credited			13 Dec 2020	
Cylinder Unit #4					
Crank Pin #4 ¹		25 Jul 2018			
Crosshead #4		21 Apr 2019			
Cylinder #4	Credited			13 Jun 2021	
Cylinder Head #4	Credited			13 Jun 2021	
Cylinder Liner #4	Credited			13 Jun 2021	
Cylinder Relief Valve #4 ¹	Credited			24 May 2021	
Exhaust Valve #4	Credited			15 Nov 2020	

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
Fuel Injection Pump #4	Credited			13 Jun 2021	
Fuel Injection Valve #4	Credited			13 Jun 2021	
Piston #4	Credited			13 Jun 2021	
Cylinder Unit #5					
Crank Pin #5 ¹		21 Apr 2019			
Crosshead #5	Credited			12 Dec 2021	
Cylinder #5	Credited			15 Nov 2020	
Cylinder Head #5	Credited			15 Nov 2020	
Cylinder Liner #5	Credited			15 Nov 2020	
Cylinder Relief Valve #5 ¹	Credited			15 Nov 2020	
Exhaust Valve #5	Credited			13 Dec 2020	
Fuel Injection Pump #5	Credited			11 Dec 2021	
Fuel Injection Valve #5	Credited			11 Dec 2021	
Piston #5	Credited			15 Nov 2020	
Main Bearing #01		21 Apr 2019			
Main Bearing #02	Credited			07 Aug 2022	
Main Bearing #03		25 Jul 2018			
Main Bearing #04		25 Mar 2019			
Main Bearing #05		26 Nov 2018			
Main Bearing #06		21 Apr 2019			
Main Thrust Bearing		21 Apr 2019			
Main Thrust Shaft		21 Apr 2019			
Scavenger Air Blower		21 Apr 2019			
Turbocharger	Credited			24 Jul 2022	
Mooring System					
Anchor Windlass (And Auxiliaries) Port ¹	Credited			12 Dec 2021	
Anchor Windlass (And Auxiliaries) Stbd ¹	Credited			12 Dec 2021	
Oil Carrier Cargo Piping System		21 Apr 2019			
Oil Carrier Cargo Piping System - Ops. Test¹		21 Apr 2019			
Cargo Oil Pump No 01 Stbd	Credited			30 Mar 2022	
Cargo Oil Pump No 02 Center	Credited			11 Dec 2021	
Cargo Piping - On Deck ¹		21 Apr 2019			
Oily Water Handling System					
Bilge Separator Oily Wtr ¹	Credited			05 Mar 2022	
Incinerator		21 Apr 2019			
Sea Water Cooling System					
Salt Water Cooling Pump #1ob Copt		25 Mar 2019			
Salt Water Cooling Pump #2ib Copt	Credited			05 Mar 2022	
Salt Water Cooling Pump Port Use	Credited			02 Jul 2022	
Seawater Piping ¹		21 Apr 2019			
Starting Air System					
Starting Air Compressor No.1 Fwd		25 Mar 2019			
Starting Air Compressor No.2 Aft		21 Apr 2019			
Starting Air Piping ¹		21 Apr 2019			
Starting Air System		25 Mar 2019			
Compressed Air Piping ¹		21 Apr 2019			
Starting Air Tank No.1 Fwd ¹		30 Oct 2018			
Starting Air Tank No.2 Aft ¹		30 Oct 2018			

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
Starting Air Tank Relief Valve No.1 Fwd ¹		30 Oct 2018			
Starting Air Tank Relief Valve No.2 Aft ¹		30 Oct 2018			
Starting Air Valves	Credited			05 Mar 2022	
Steam Piping System					
Manuvering Controls		26 Nov 2018			
Steam Lines ¹		21 Apr 2019			
Steering Gear System					
Steering Gear Control System		26 Nov 2018			
Steering Gear Unit ¹		26 Nov 2018			
Steering Gear Unit - Pipes		26 Nov 2018			
Steering Gear Unit - Pumps		26 Nov 2018			
Steering Gear Unit - Relief Valve		26 Nov 2018			
Stern Tube Lubricating System					
Stem Tube Lubricationg Piping ¹		21 Apr 2019			
Stern Tube Lube Oil Cooler ¹	Credited			02 Jul 2022	
Stern Tube Lube Oil Pump No 01 Outbd		30 Oct 2018			
Stern Tube Lube Oil Pump No 02 Inbd		24 Jul 2018			

Legend

¹ : Items that cannot be credited by the vessel's Chief Engineer. For heat Exchangers and Unfired Pressure Vessels this only applies if the design pressures is over 6.9 bar (7 kgf/cm², 100 psi).

Parts List Summary

Survey Cycle Years	1	2	3	4	5
Inspections Completion Ratio (%)	0	5	28	8	0
Number of Inspections Completed/ Remaining Count	0/240	11/229	78/162	97/143	97/143

ABS Approved Programs	PMP-PM	PMP-CM	RBI	RCM	None	TOTAL
Number of Items	0	0	0	0	232	232
Ratio of Items on PMP program	0/232 Or 0.0%					

Note:

1. An item can have multiple inspection due dates.
2. Please note items with tags 'RCM' and 'RBI' are NOT include in the ratio for PMP items.
3. Survey Cycle Years are yearly intervals from the associated cycle start date to 12 months from cycle start date, e.g. 'Year 1', is equivalent to cycle start date +12 months and so on till the 'Year 5'.
4. The above table is only displayed, when the service type is 'Classification' and the survey type is 'Special' and the mode is 'Continuous' and there are class items associated to the survey type.
5. The class item inspections, total count are items with inspection that are checked as class required inspection.
6. Inspection Completion Ratio - is the ratio of inspections completed per year against the total inspections assigned to the survey type/cycle.

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Survey Parts : Special Periodical Survey - Automation 4

Machinery Item(s)	Status	Due Date	Extended Date	Done Date	ABS Approved Program
Automation Control System		08 May 2019			
Dock Trials		08 May 2019			
Manoeuvring Control And Monitoring System					
Automation Control Actuators		08 May 2019			
Automation Insulation Resistance Control Actuators		08 May 2019			
Automation Insulation Resistance Control Motors		08 May 2019			

Legend

¹ : Items that cannot be credited by the vessel's Chief Engineer. For heat Exchangers and Unfired Pressure Vessels this only applies if the design pressures is over 6.9 bar (7 kgf/cm², 100 psi).

Survey Parts : Special Periodical Survey - Hull 4

Space Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date	Condition
Habitable						
Accommodation Spaces	Overall Survey		08 May 2019			
Storage Spaces	Overall Survey		08 May 2019			
Machinery						
Machinery &/Or Boiler Room Spaces	Overall Survey		08 May 2019			
Main Pump Room	Overall Survey		08 May 2019			
Space Arrangement						
Main Hull	Thk. Meas		08 May 2019			
Plating In Way Of Airports	Overall Survey		08 May 2019			
Tank - Ballast						
Aft Peak Tank C	Closeup Survey		08 May 2019			Good
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Ballast Tank 01 P	Closeup Survey		08 May 2019			Fair
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Ballast Tank 01 S	Closeup Survey		08 May 2019			Fair

ABS Survey Manager Survey Status

Name : **CHIMBORAZO**

Class Number : **9936460**

Status : **In-Operation - Lightering Service, Active, Classed**

IMO Number : **9174581**

Space Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date	Condition
Ballast Tank 02 P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			Fair
Ballast Tank 02 S	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			Fair
Ballast Tank 03 P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			Fair
Ballast Tank 03 S	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			Fair
Ballast Tank 04 P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			Fair
Ballast Tank 04 S	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			Fair
Fore Peak Tank C	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			Good
Tank - Cargo Oil						
Cargo Oil Tank 01 P	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Cargo Oil Tank 01 S	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Cargo Oil Tank 02 P	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Cargo Oil Tank 02 S	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Space Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date	Condition
Cargo Oil Tank 03 P	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
Cargo Oil Tank 03 S	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
Cargo Oil Tank 04 P	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
Cargo Oil Tank 04 S	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
Cargo Oil Tank 05 P	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
Cargo Oil Tank 05 S	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
Cargo Oil Tank 06 P	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
Cargo Oil Tank 06 S	Press. Test		08 May 2019			
	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
			08 May 2019			
Tank - Diesel Oil						
Diesel Oil Service Tank P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Double Bottom Diesel Oil Tank P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Double Bottom Diesel Oil Tank S	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Tank - Fresh Water						
Fresh Water Tank P	Overall Survey		08 May 2019			

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Space Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date	Condition
Fresh Water Tank S	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
	Overall Survey		08 May 2019			
Stern Tube Cooling Water Tank C	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
	Press. Test		08 May 2019			
Tank - Fuel Oil						
Heavy Fuel Oil Bunker Tank 01 P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Heavy Fuel Oil Bunker Tank 01 S	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Heavy Fuel Oil Bunker Tank 02 P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Heavy Fuel Oil Bunker Tank 02 S	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Heavy Fuel Oil Overflow Tank P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Heavy Fuel Oil Service Tank P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Heavy Fuel Oil Settling Tank P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Tank - Lubricating Oil						
Cylinder Oil Tank P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Generator Engine Lube Oil Storage Tank P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Main Engine Lube Oil Settling Tank P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Main Engine Lube Oil Storage Tank P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Main Engine Lube Oil Sump Tank C	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Space Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date	Condition
	Press. Test		08 May 2019			
Tank - NOT SPECIFIED						
Chain Locker	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
Tank - Slop						
Slop Tank P	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Slop Tank S	Closeup Survey		08 May 2019			
	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Tank - Sludge						
Sludge Tank P	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Tank - Waste Water						
Bilge Holding Tank C	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			
Oily Bilge Tank C	Overall Survey		08 May 2019			
	Piping Exam/Test		08 May 2019			
	Press. Test		08 May 2019			

Structural Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date	Condition
Structural System						
Bottom Plating	Examination		08 May 2019			
Deck	Examination		08 May 2019			
End Blkhd Of Cargo-Tank Testing (If Applicable) AFT	Examination		08 May 2019			
End Blkhd Of Cargo-Tank Testing (If Applicable) FWD	Examination		08 May 2019			
Side Shell Plating	Examination		08 May 2019			
Steering Gear Flat	Examination		08 May 2019			

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Outfitting Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date
--------------------	-----------------	--------	----------	---------------	-----------

Hull Fitting

Hawse Pipe (Count: 1)	Examination		08 May 2019		
Stern Frame	Examination		08 May 2019		

Vents

Airpipe Closing Device	Examination		08 May 2019		
------------------------	-------------	--	-------------	--	--

Machinery Item(s)	Status	Due Date	Extended Date	Done Date	ABS Approved Program
-------------------	--------	----------	---------------	-----------	----------------------

Bilges & Drain Wells ¹		08 May 2019			
Chain Locker Pumping System		08 May 2019			
Bilge Piping ¹		08 May 2019			

Mooring System

Anchor (Starboard)		08 May 2019			
Anchor Chains		08 May 2019			

Sanitary Water System

Sanitary Overboard Discharges ¹		08 May 2019			
--	--	-------------	--	--	--

Legend

¹ : Items that cannot be credited by the vessel's Chief Engineer. For heat Exchangers and Unfired Pressure Vessels this only applies if the design pressures is over 6.9 bar (7 kgf/cm², 100 psi).

Cargo Gear Survey

Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date
---------	-----------------	--------	----------	---------------	-----------

Crane1	Renewal. Insp. Annual. Insp.		07 Aug 2021 22 Apr 2018		
--------	---------------------------------	--	----------------------------	--	--

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Class Recommendations - Open

No open class recommendations have been reported as of the date of this report.

Class Recommendations - In Progress

No in progress class recommendations have been reported as of the date of this report.

Statutory Deficiencies - Open

No open statutory deficiencies have been reported as of the date of this report.

Statutory Deficiencies - In Progress

No in progress statutory deficiencies have been reported as of the date of this report.

Special Findings - Open

No open special findings have been reported as of the date of this report.

Special Findings - In Progress

No in progress special findings have been reported as of the date of this report.

Attendance History - Last 12 months

Port Office	Report Number	Last Visit Date	Status
Valparaiso	VP3360517	07 Aug 2017	
	Report Number	Survey	Status
	VP3360517-E	Annual Automation Survey 3	Completed
	VP3360517-C	Annual Hull Survey 3	Completed
	VP3360517-B	Annual Machinery Survey 3	Completed
	VP3360517-A	Cargo Gear Survey	Completed
	VP3360517-F	Other Survey (Statutory)	Completed
	VP3360517-D	Special Continuous Survey - Machinery 4	Commenced
San Francisco, CA	SF3325476	10 May 2017	
	Report Number	Survey	Status
	SF3325476-B	Special Continuous Survey - Machinery 4	Commenced
	SF3325476-A	Survey for Compliance - Class	Completed
Balboa	BL3319296.R1	22 Apr 2017	
	Report Number	Survey	Status
	BL3319296.R1-B	Boiler Survey - Auxiliary Water Tube Boiler S	Completed

ABS Survey Manager Survey Status

Name : **CHIMBORAZO** Class Number : **9936460**
 Status : **In-Operation - Lightering Service, Active, Classed** IMO Number : **9174581**

Port Office	Report Number	Last Visit Date	Status
	BL3319296.R1-A	Cargo Gear Survey	Completed
	BL3319296.R1-D	Intermediate IAPP Annex VI Survey 4	Completed
	BL3319296.R1-C	Special Continuous Survey - Machinery 4	Commenced
Balboa	BL3322517	22 Apr 2017	
	Report Number	Survey	Status
	BL3322517-A	Port State Control Survey	Completed
Balboa	BL3279108	02 Feb 2017	
	Report Number	Survey	Status
	BL3279108-A	Boiler Survey - Waste Heat Boiler	Completed
Balboa	BL3243190	25 Dec 2016	
	Report Number	Survey	Status
	BL3243190-D	Boiler Survey - Auxiliary Water Tube Boiler P	Completed
	BL3243190-E	Boiler Survey - Auxiliary Water Tube Boiler S	Commenced
	BL3243190-F	Boiler Survey - Waste Heat Boiler	Commenced
	BL3243190-C	Drydocking Survey	Completed
	BL3243190-K	Initial Survey Anti-Fouling System	Completed
	BL3243190-B	Intermediate Hull Survey 4	Completed
	BL3243190-H	Other Survey (Statutory)	Completed
	BL3243190-G	Repair Survey (Class)	Completed
	BL3243190-A	Special Continuous Survey - Machinery 4	Commenced
	BL3243190-I	Statement of Fact Survey	Completed
	BL3243190-J	Survey for Compliance - Class	Completed

ABS Survey Manager Survey Status

Name : **CHIMBORAZO**

Class Number : **9936460**

Status : **In-Operation - Lightering Service, Active, Classed**

IMO Number : **9174581**

Request For Attendance

To ABS Office At: _____ ABS Fax No: _____

Attn: Surveyor-in-Charge

Requestor's Name : _____

Requestor's Company : _____

Requestor's Company Address: _____

Requestor's Tel. #: _____

Local Contact Details : _____

Billing Customer Name : _____

Billing Customer Address : _____

Name : **CHIMBORAZO**

ABSID : **9936460**

Customer W.O/P.O. (if any) : _____

Date and Time of Survey : _____

Place of Survey : _____

We hereby request attendance for the attached surveys/items checked. If any surveys/items are not checked, please explain in the reason for each :

Requestor's Signature

ABS Survey Manager Survey Status

Name : **CHIMBORAZO**

Class Number : **9936460**

Status : **In-Operation - Lightering Service, Active, Classed**

IMO Number : **9174581**

*Note: The survey overdue date includes the window of time allotted for completion of annual and intermediate surveys, as applicable.

ADDITIONAL: List any additional surveys/items that are not checked above that you wish to include at this time.
